

PARTS BULLETIN



Continental Girbau • Girbau Industrial • Sports Laundry Systems
Onepress • Poseidon Textile Care • LG Commercial • Econo

Reference		Date
PB-153	Door Gasket Change	7/14/22
Product	EH060, EH070, EH080, RMG070	

Summary

The door gasket on the EH060, EH070, EH080, and RMG070 has been changed to a new door gasket (**p/n 11916434**). All applicable equipment manufactured after August 1st 2022 will have this new door gasket. The new door gasket will be available as a service part.

The new gasket cannot be used on the EH040 and RMG055.



The part number for the **new gasket** is **11916434**. The original gasket (p/n 563346) will still be an active part number.

Differences in the Door Gasket

1. Different durometer material
 - a. Material is more elastic, creating a tighter seal
2. Different profile
 - a. The new gasket has a tapered profile to better seal with the front shell opening



3. **NOTE: Door glass spring and door shim removal**
 - a. The door glass spring cannot be used with this new door gasket.
 - b. The door shim cannot be used with the new door gasket.
 - c. The door catch shims cannot be used with the new door gasket.



Always follow the warnings and procedures in the corresponding equipment instruction manual.